



DESIGN 5

A R C H I T E C T S



WYNSTAY, MOUNT WILSON

PHOTOGRAPHIC RECORD OF WATER TANK STANDS PRIOR TO DEMOLITION

11 May 2009

Photographs taken by Design 5 – Architects on 2 March 2009 unless otherwise noted.



Aerial photograph of the site showing location of water tank stands. (Source: Google Maps 2009)

Design 5 - Architects Pty Ltd ACN 090 066 194 ABN 22 090 066 194
5 Queen Street, Chippendale NSW 2008
Tel (02) 9319 1855 (02) 9319 0836 Fax
E-mail: design5@design5.com.au
Nominated Architect – Alan Croker, Registration No 4693
Catherine Forbes 5861 Letizia Coppo-Jones Robert Gasparini 7614



Figure 1: Approach from the driveway, looking east. The water tank stands can be seen behind the Stables



Figure 2: Continuing up the driveway.



Figure 3: Continuing up the driveway.



Figure 4: Continuing up the driveway.



Figure 5: Looking north-east from the gate. The water tank stands adjacent to the Stables.



Figure 6: Water tank stands viewed from inside the gate.



Figure 7: Looking north-west, with the original timber cottage in the foreground, and the stables in the background.



Figure 8: Looking north-west, with the original timber cottage in the foreground, and the stables in the background.



Figure 9: Looking south, with the Stables in front of the water tank stands.



Figure 10: Looking south-east with the Stables in the foreground and the timber cottage in the background.



Figure 11: The water tank stands leaning away from the Stables, towards the timber cottage.



Figure 12: Water tank stands in front of the Stables.



Figure 13: Timber platform at the top of the water tank stands.



Figure 14: Timber platform at the top of the water tank stands.



Figure 15: Detail of the framing.



Figure 16: Corroded framing members.
(Source: Hughes Trueman 2009)



Figure 17: Detail of the framing. (Source: Hughes Trueman 2009)



Figure 18: Severed leg at base of tank stand
(of the eight tank stand legs, only three are providing support).



Figure 19: Detail of the framing.



Figure 20: Severed leg at base of tank stand.



Figure 21: Severed leg at base of tank stand.



Figure 22: Leg at base of tank stand rusted off at ground level.



Figure 23: Movement at the base of the tank stand as it leans towards the south.



Figure 24: Detail of the framing. Note the corrosion in the diagonal bracing.